

## EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
S1	344	(417/500).OCLS.	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/03/24 08:17
S2	1	("4412519").PN.	USPAT	OR	OFF	2008/03/24 12:41
S3	1	("5181585").PN.	USPAT	OR	OFF	2008/03/24 12:44
S4	383	diesel with fuel with lubrication	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/24 13:43
S5	61	S4 with pump	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/24 13:43
S6	2	("6540486").PN.	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/03/24 15:13
S7	12	("4223558"   "4323097"   "4941809"   "5015157"   "5020980"   "5044889"   "5102310"   "5246354"   "5279210"   "5482448"   "5863187"   "6224347").PN.	US_PGPUB; USPAT; USOCR	OR	ON	2008/03/24 15:14
S8	1	("6322336").PN.	USPAT	OR	OFF	2008/03/24 15:29

S9	21	"rack and pinion" with piston	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/24 15:46
S10	9882	"worm gear" and piston	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/24 15:58
S11	1016	"worm gear" with piston	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/24 15:59
S12	18	S11 and "stepping motor"	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/24 16:00
S13	344	(417/500).OCLS.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/03/25 15:32
S14	14	S13 and step\$4 near2 motor	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/25 15:32
S15	28707	gear near2 cam	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/25 15:48
S16	4563	S15 and piston	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/25 15:48

S17	1484	S16 and piston with reciproca\$4	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/25 15:48
S18	139	S16 and piston with reciproca\$4 with (gear near2 cam)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/25 15:48
S19	344	(417/500).CCLS.	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/03/26 08:34
S20	0	S19 and "Hall sensor"	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/26 08:34
S21	4	S19 and "position sensor"	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/26 08:34
S22	9	Huss.in. near2 roll. in.	US_PGPUB; USPAT	OR	ON	2008/03/26 10:15
S23	291	worm near2 gear near5 magnet\$5	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/09/18 11:56
S24	939	pump.clm. and (distributor valve). clm. and rotat\$3. clm. and thread\$2. clm.	US_PGPUB; USPAT	OR	ON	2008/09/19 09:29
S25	367	pump.clm. and (distributor valve). clm. and (rotat\$3. clm. with thread \$2.clm.)	US_PGPUB; USPAT	OR	ON	2008/09/19 09:29

S26	160	(417/442).CCLS.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/09/24 08:18
S27	602	(417/494).CCLS.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/09/24 08:26
S28	209	S27 and (thread \$3 screw\$3)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/09/24 08:26
S29	361	(417/502).CCLS.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/09/24 08:41
S30	109	S29 and (tthread \$3 screw\$3)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/09/24 08:42
S31	826	(74/127).CCLS.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/09/24 08:51
S32	1362	(74/409).CCLS.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/09/24 09:15
S33	580	S32 and (tthread \$3 screw\$3)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/09/24 09:17

9/24/2008 9:33:17 AM

C:\Documents and Settings\pstimpert\My Documents\EAST\Workspaces\10722165.wsp